



BINK'S AUTO REPAIR, LLC



TEL: 508-693-2168 • FAX: 508-696-8709 • P. O. BOX 3218 • WINTHROP AVENUE • OAK BLUFFS, MA 02557

August 31, 2021

Inspection of 49cc 2018 GSC Venture moped MA #33991

Brakes:

Rear new caliper and pads
Front 60 to 70% of pad material left

Tires:

Rear -new
Front 40 to 50%

Suspension:

Front shock shows some sign of seepage but fully functional

Rear suspension and drive line intact

Engine has had significant overhaul, with new piston housing and water pump. Some minor oil leaks on base.

Upon inspection found ignition switch in run position with steering lock disabled.

Inspection after disassembling the steering tube showed no cracks or binding and the bearings were well lubricated and torqued.

Only signs of damage were collision related.

William N deBettencourt III